

Crank Sensor Wiring 60-2 to 36-1

Pin Outs on Crank /Harness	Sensor Type	1	2	3
60-2 (Vauxhall)	Vauxhall	Return	Signal	Screen
60-2 (Vauxhall)	Ford (not recommended)	Return	Signal	N/C
36-1 (Ford)	Ford	Signal	Return	N/C
36-1 (Ford)	Vauxhall	Signal	Return	Screen

